




Winchester and District Canoe Club Risk Assessment

Date:	30-06-2025
-------	------------

Assessors Name:	Mike Creagh	Review Date:	01/07/2026
-----------------	-------------	--------------	------------

Description of assessment	Building Risk Assessment
---------------------------	--------------------------

Location Details	Devil's Island – North Walls Park, Winchester. <u>What Three Words Location loses.cared.plotter</u> 
------------------	---

Construction of Building	Wooden Frame Building – No Asbestos known to be present in Building
--------------------------	---

What are the hazards?	Who might be harmed and how?	What are you already doing to control the risks?	What further action do you need to take to control the risks?	Who needs to carry out the action?	When is the action needed by?
Electrical Safety	All Electrocution	Electrical Inspection testing Portable Appliance Testing Visual Checks to be carried out on all equipment	Electrical Inspection needs to be carried out every 5 years Checks to be carried out before use	All	June 2029 On going
Fire	All Risk of serious / fatal injury through smoke inhalation or burns	Emergency procedure posted within the club hut. In date fire extinguishers to be placed within the kitchen and club hut. Dates recorded and reviewed periodically. Fire Blanket in kitchen area of club. Fire escape signage to showing all exit routes. Fire door must be unlocked as part of the unlocking procedure each time the club building is in use. Fire alarms to be installed within the club hut and boat hut area. No hot works to be carried out within the building.	1x New fire blanket to be purchased for kitchen.		

What are the hazards?	Who might be harmed and how?	What are you already doing to control the risks?	What further action do you need to take to control the risks?	Who needs to carry out the action?	When is the action needed by?
Storage of Kayaks. Kayaks falling, muscular injury.	All	Instruction is given on using the racking. Supervision of novice paddlers with adults helping young paddlers to lift boats.	A new system of racking should be investigated.	committee	Dec 2025
Storage of Canoes, muscular injury	All	Instruction is given on using the racking. Supervision of novice paddlers with adults helping young paddlers to lift boats. Two people are needed to take canoes from racking.	The racking is adequate		
	All				
Storage of paddles, paddles falling	All	Paddles are stored in adequate racking.			

What are the hazards?	Who might be harmed and how?	What further action do you need to take to control the risks?	What further action do you need to take to control the risks?	Who needs to carry out the action?	When is the action needed by?
Slips, trips and falls	All	The walkways and club areas to be kept clear of obstacles. Boats should be placed on grass not on concrete directly outside of club.		Everyone	

